

## AGENCY OF HUMAN SERVICES

DEPARTMENT OF DISABILITIES, AGING AND INDEPENDENT LIVING
Division of Licensing and Protection

103 South Main Street, Ladd Hall Waterbury VT 05671-2306 http://www.dail.vermont.gov

Voice/TTY (802) 241-2345

To Report Adult Abuse: (800) 564-1612

Fax (802) 241-2358

January 4, 2012

Ms.. Charlene Bedor, Administrator Administrator Redstone Villa 7 Forest Hill Drive St Albans, VT 05478-1615

Provider #: 475055

Dear Ms.. Bedor:

Enclosed is a copy of your acceptable plans of correction for the Life Safety Code survey conducted on **October 25, 2011**. Please post this document in a prominent place in your facility.

We will follow up to verify that substantial compliance has been achieved and maintained. If we find that your facility has failed to achieve or maintain substantial compliance, remedies may be imposed.

Sincerely,

Pamela M. Cota, RN

amlaMCotaRN

Licensing Chief

PC:ne

Enclosure



DEPARTMENT OF HEALTH AND HUMAN SERVICES

CENTERS FOR MEDICARE & MEDICAID SERVICES

#4758 P.006/009

PRINTED: 11/30/2011 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - BUILDING 01		(X3) DATE SURVEY COMPLETED	
475065		B. WING		10/25/2011		
NAME OF PROVIDER OR SUPPLIER REDSTONE VILLA				REET ADDRESS, CITY, STATE, ZIP CODE FOREST HILL DRIVE ST ALBANS, VT 06478		
· (X4) ID PREFIX TAG	FIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(5) LETION
K 000	INITIAL COMMENTS		K 000			
K 015 SS=D K 018 SS=D	A Life Safety Code inspection was completed on 10/25/11 by the Department of Public Safety. The following are violations of the Life Safety Code requirements for Nursing Homes.  NFPA 101 LIFE SAFETY CODE STANDARD  Interior finish for rooms and spaces not used for corridors or exitways, including exposed interior surfaces of buildings such as fixed or movable walls, partitions, columns, and ceilings, has a flame spread rating of Class A or Class B. (In fully sprinklered buildings, flame spread rating of Class A, Class B, or Class C may be continued in use within rooms separated in accordance with 19.3.6 from the access comdors.) 19.3.3.1, 19.3.3.2  This STANDARD is not met as evidenced by: Based on observation, the facility failed to assure adequate interior finish for 2 applicable resident rooms. Findings include:  Per observation on 10/25/11, accompanied by Maintenance Staff, Rooms 5 and 15 have damaged walls. This reduces the interior finish rating of the rooms.  NFPA 101 LIFE SAFETY CODE STANDARD		K 015 1. How will corrective action be accomplished those residents found to have been affected by deficient practice?  The damaged walls in room #6 and room #were repaired on 10/28/2011.  2. How will the facility identify other residents have the potential to be affected by the same deficient practice?  Residents were not harmed by this alleged deficient practice.  3. What measures will be put into place or system thanges made to consure that the deficient practice not recur?  Maintenance Director & Housekeeping Staff will recducated on routine repairs on walls and desurfaces by 12/12/2011.  4. How will the facility monitor its corrective action ensure that the deficient practice will not recur?  Random Andits by Administrator/Designee on wand door surfaces.  Results will be reviewed at Quarterly QA Meeting  5. Include dates when a corrective action will completed.  Administrator/Designee will be responsible monitoring to anyre compliance with POC regulatory requirements by 12/12/2011.  KOIS POC accopted 12/12/01 J Benard   PWC Colling to the practice?  All fire doors were tested and adjusted as needed 11/1/2011.		death having me deficient ged deficient ged deficient for systemic practice will be and door sive actions to recur? gnee on wall Meeting ction will be ponsible for h POC and mplished for lected by the	
	wood, or capable of	of 1% inch solid-bonded core f resisting fire for at least 20 sprinklered buildings are only				
ABORATORY DIRECTOR'S OR PROVIDERSUPPLIER REPRESENTATIVE'S SIGNATURE  Advantstrator 12/7/11						

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-98) Previous Versione Obsolete

Event ID: WUDB21

Facility ID; 476056

if continuation sheet Page 1 of 4



**DEPARTMENT OF HEALTH AND HUMAN SERVICES** 

#4758 P.007/009

PRINTED: 11/30/2011 FORM APPROVED OMB NO. 0938-0391

CENTER	CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391								
		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A BUILDING 01 - BUILDING 01		.4	(X3) DATE SURVEY COMPLETED			
	475055		B. WIN	B. WING		10/25/2011			
NAME OF PROVIDER OR SUPPLIER REDSTONE VILLA			·	7 F	ET ADDRESS, CITY, STATE, ZIP CODE FOREST HILL DRIVE ALBANS, VT 05478				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		ULD BE	(X5) COMPLET DATE	ON		
K 018	Continued From page 1 required to resist the passage of smoke. There is no impediment to the closing of the doors. Doors are provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.6 are permitted. 19.3.6.3 Roller latches are prohibited by CMS regulations in all health care facilities.		K	018	2. How will the facility identify other residents having the potential to be affected by the same deficient practice? All residents have the potential to be affected by this alleged deficient practice.  3. What measures will be put into place or systemic changes made to ensure that the deficient practice will not recur?  Maintenance Director will be reeducated on routine maintenance checks of fire door closure and latching by 12/12/2011.				
				1 1 1	1. How will the facility monitor its correct ensure that the deficient practice will not Maintenance Director will test fire door adjust as needed. Random audits by Add designee will be conducted on proper fire and latching. Results will be reviewed QA meeting.	recur? s weekly and ninistrator or door closure at quarterly			
,	Based on observative doors are fully of facility. Findings in Per observation on Maintenance Staff, near the kitchen did	s not met as evidenced by: tion, the facility failed to assure operable in one area of the clude:  10/25/11, accompanied by the fire doors in the corridor I not close and latch. FETY CODE STANDARD	K	056	completed.  Administrator/Designee will be real monitoring to assure compliance wit regulatory requirements by 12/12/2011.  KOIB POC accepted 12/20/11  J Benard   KWataku  L. Haw will corrective action be accombose residents found to have been affected.	ponsible for h POC and			
SS=D	installed in accordator the Installation of provide complete or building. The system accordance with Ni Inspection, Testing Water-Based Fire is supervised. There supply for the system.	ratic sprinkler system, it is note with NFPA 13, Standard of Sprinkler Systems, to overage for all portions of the m is properly maintained in FPA 25, Standard for the and Maintenance of Protection Systems. It is fully is a reliable, adequate water m. Required sprinkler and with water flow and tamper	.**	2 1 3 6 0	leficient practice? Coiling tile was reset by Maintenance id/25/2011.  L. How will the facility identify other residue potential to be affected by the same cice? All residents have the potential to be affilieged deficient practice.  What measures will be put into place hanges made to ensure that the deficient pot recur?  Jelotrenance Director will be reeducted on a sintenance by 12/12/2011.	Director on dents having me deficient ected by this or systemic practice will			

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

(X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED . A. BUILDING 01 - BUILDING 01 B. WING 475055 10/25/2011 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 7 FOREST HILL DRIVE REDSTONE VILLA ST ALBANS, VT 05478 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX PREFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) K 056 4. How will the facility monitor its corrective actions to K 056 Continued From page 2 ensure that the deficient practice will not recur? switches, which are electrically connected to the Maintenance Director will check celling files during daily rounds of building to ensure all tiles are set building fire alarm system. property. Results will be reviewed at quarterly QA meeting. 5. Include dates when a corrective action will be completed. This STANDARD is not met as evidenced by: Administrator/Designee will be responsible for Based on observation, the facility failed to assure monitoring to susure compliance with POC and that the building is maintained to assure proper regulatory requirements by 12/12/2011. functioning of the sprinkler system in one area of KOS6 POC accepted 12/20/11 the building. Findings include: JBenard/ AMCOTARN Per observation on 10/25/11, accompanied by Maintenance Staff, a portion of the ceiling tile in the closet located across from the employee break room had dropped out, impacting the timely operation of the sprinkler head. K 130 NFPA 101 MISCELLANEOUS K 130 I. How will corrective action be accomplished for those residents found to have been affected by the SS=D deficient practice? OTHER LSC DEFICIENCY NOT ON 2786 The primary air on the stove was corrected by a gas repairmen on 10/26/2011. The handrall was replaced on 10/25/2011. 2. How will the facility identify other residents baving This STANDARD is not met as evidenced by: the potential to be affected by the same delicient Based on observation, the facility failed to assure practice? compliance with other fire safety/life safety standards. Findings include: No residents were affected by the alleged deficient practice. Residents who use the handralts for motivation have the 1. Per observation on 10/25/11, accompanied by potential to be affected by the alleged deficient practice. Maintenance Staff, the primary air for the stovetop burners on the kitchen stove are out of 3. What measures will be put into place or systemic adjustment as evidenced by long yellow flames. changes made to ensure that the deficient practice will not recur? All dietary staff and Maintenance Director will be 2. Per observation on 10/25/11, accompanied by reeducated on proper stove burner functioning by Maintenance Staff, a piece of the corridor 12/12/2011. handrail located across the corridor from the Beauty Station was found broken and taped Maintenance Director will be reeducated on handrail safety and repair by 12/12/2011.

PRINTED: 11/30/2011

DEPARTMENT OF HEALTH AND HUMAN SER	VICES
CENTERS FOR MEDICARE & MEDICAID SERV	

FORM APPROVED OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** COMPLETED A. BUILDING 01 - BUILDING 01 B. WING 475055 10/25/2011 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 7 FOREST HILL DRIVE REDSTONE VILLA ST ALBANS, VT 05478 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX EACH CORRECTIVE ACTION SHOULD BE PREFIX PATE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG **DEFICIENCY** 4. How will the facility monitor its corrective actions to ensure that the deficient practice will not recur? :K 130 Continued From page 3 Administrator/Designee will conduct daily audits of together. stove burner functioning. Results will be reviewed at quarterly QA meeting. K 147 NFPA 101 LIFE SAFETY CODE STANDARD SS=D Administrator/Designee will conduct random audits of Electrical wiring and equipment is in accordance handrails monthly. Results will be reviewed at quarterly QA meeting. with NFPA 70, National Electrical Code. 9.1.2 5. Include dates when a corrective action will be completed. Administrator/Designee will be responsible for monitoring to This STANDARD is not met as evidenced by: assure compliance with POC and regulatory requirements by Based on observation, the facility failed to ensure 12/12/2011 K130 POC accepted 12/20/11 JBonard / AMEDIARN electrical wiring is in accordance with NFPA 70. National Electrical Code 9.1.2 in 2 areas of the 1. How will corrective action be accomplished for facility. Findings include: those residents found to have been affected by the K147 delicient practice? Outlets located near the water coolers were Per observation on 10/25/11, accompanied by replaced with GFCI outlets on 10/27/2011. Maintenance Staff, the water coolers located in the second floor foyer and near the first floor 2. How will the facility identify other residents baving the potential to be affected by the same deficient Nurses Station are plugged into outlets that are practice? not GFCI (Ground Fault Circuit Interrupter) No residents were affected by this alleged deficient protected. practice. 3. What measures will be put into place or systemic changes made to ensure that the deficient practice will not recur? Maintenance Director will be reeducated on outlett near water supplies by 12/12/2011. 4. How will the facility monitor its corrective actions toensure that the deficient practice will not recur? Administrator/Designee will monitor outlets near water supplies for future projects. 5. Include dates when a corrective action will be completed. Administrator/Designee will be responsible for monitoring to assure compliance of POC and regulatory requirements by KI47 POC accepted 12/20/11

Jeenard | Prostain

Redstone Villa, (the "Provider") submits this plan of correction, (POC), in accordance with specific regulatory requirements. It shall not be construed as an admission of any alleged deficiency cited.

The Provider submits this POC with the intention that it be inadmissible by any third party any civil or criminal action against the Provider or any employee, agent, officer, director or shareholder of the Provider. The Provider hereby reserves the right to challenge the findings, that are relied upon to adversely influence or serve as a basis, in any way, for the selection and / or imposition of future remedies, or for any increase in future remedies, whether any such remedies are imposed by the Centers for Medicare and Medicaid Services ("CMS"), the State of Vermont or any other entity.

Any changes to Provider Policy or Procedure should be considered to be subsequent remedial measures as that concept is employed in Rule 407 of the Federal Rules of Evidence and should be inadmissible in any proceedings on that basis.